



1	dust cover of spindle	1	21	Screw M5x10	2	41	Timing switch	1
2	WoodruffKey4x5x13	1	22	Armature	1	42	Right Handle	1
3	Output Spindle	1	23	Shield	1	43	Rubber Sleeve	1
4	Screw M4x16	4	24	Bearing608	1	44	Cord	1
5	Spring Washer	4	25	Rubber Bush	1	45	Screw ST4x16	4
6	Fore Cover	1	26	Fan Guide	1	46	copper tubing	2
7	Bearing 6001	1	27	ScrewST4x65	2	47	2.8 Wiring Inserted Piece	2
8	Screw M5x10	2	28	Stator	1	48	Tridentate Buckle	2
9	Big Gear	1	29	Chassis Fastener	1	49	Screw M8x15	2
10	Wave Spring Washers $\phi 10$	1	30	Plastic Housing	1			
11	Circlip For Shaft 10	1	31	Name plate(right and left)	1			
12	Ogalle Bearing	1	32	Brush Hold(right and left)	2	501	D assistant handle	1
13	Reducer	1	33	Conbar Brush(right and left)	2	502	180MM bonnet	1
14	Screw ST4x25	4	34	Carbon Cap(right and left)	2	503	Side Handle	1
15	Brake Pin	1	35	Screw ST 4X10(right and left)	2	504	Inner hexagon spanner	1
16	Spring	1	36	Spring	2			
17	"E" Ring 4	1	37	Left Handle	1			
18	Scalp fastener	1	38	Cord Clip	1			
19	Small Gear	1	39	Screw ST 4X12	2			
20	Bearing 6001	1	40	Switch	1			